



**LOOKING GLASS  
FACTORY**



Getting Started with  
**Looking Glass Portrait**


Advance Beta Edition

# Setup + Viewing Holograms

## Standalone Mode


### 1 Attach the base plate.

- Remove the base plate off of the back of the unit.
- Align the plate openings onto the 2 studs - the 2 foam pads should be facing down.
- Slide the plate forward to lock it in place.



### 2 Attach the USB-C Cable.

- Connect the included USB-C cable to Looking Glass Portrait's USB-C port.
- (If provided) Install your conversion head into the provided adapter.
- Attach the USB-C cable to the adapter and plug into a wall outlet.




The LED indicator will pulse white to indicate that your unit is ready for Standalone Mode.

### 3 Switch Looking Glass Portrait ON to Standalone Mode.

- Press the ON/OFF button.
- Wait 5-8 seconds for Looking Glass Portrait to boot up.

To switch Looking Glass Portrait OFF, hold the ON/OFF button for 2 seconds. Only disconnect the power after switching off the unit.



#### 4 View & navigate through the included demo reel.


- When switched ON, the unit will automatically loop through the included demo reel.
- Manual Button Controls:

**Forward**

**Back**

**Play-Pause-Loop**

- To freeze frame a demo, tap Play-Pause-Loop.
- To loop a particular demo on repeat, hold Play-Pause-Loop for 2 seconds.
- To return to cycling through all demos in the reel, tap Forward or Back.



#### 5 Adjust the edge lighting (if needed).

- Use the Edge Lighting button to scroll through 4 light levels + OFF.

## Hoo! Ray!

The included demo reel you just experienced is just the beginning.  
Start making content of your own by heading to the link below:

**[HTTP://LOOK.GLASS/PORTRAIT-START](http://look.glass/portrait-start)**

\* Note that some software may not be available by the time your  
Advance Beta Looking Glass Portrait gets to you.  
Once it is ready, we will send out a separate note.

# Setup + Creating Holograms

## Desktop Mode

### 1 Connect the USB-C cable to your Windows / Mac.

- (If you were in Standalone Mode) Disconnect the USB-C cable from your power adapter.
- Connect the USB-C cable to your computer USB-C port.

### 2 Connect the HDMI cable.

- Connect the HDMI cable to your computer's HDMI port.
- Connect the HDMI cable to Looking Glass Portrait's HDMI port.


The LED indicator will pulse blue to indicate that your unit is ready for Desktop Mode.

### 3 Switch Looking Glass Portrait ON to Desktop Mode.

- Press the ON/OFF button.

### 4 Start creating content.

- Go to **[HTTP://LOOK.GLASS/PORTRAIT-START](http://LOOK.GLASS/PORTRAIT-START)**



**IMPORTANT:** Whether you're in Desktop or Standalone Mode, switch off your Looking Glass Portrait before unplugging from the power source. You can do this by holding the ON/OFF button for 2 seconds.



**LOOKING GLASS  
FACTORY**

Looking Glass Factory (US)  
190 West St, Brooklyn NY, 11222 USA  
[www.lookingglassfactory.com](http://www.lookingglassfactory.com)

© 2021. Looking Glass Factory. All Rights Reserved.  
The Looking Glass Logo Design is a trademark of Looking Glass Factory (US).  
Looking Glass Portrait is protected by patents granted and pending around the world.  
Looking Glass Portrait - Getting Started Guide 2-01 RBD13