

TRANSVIDEO S.A. Zone Industrielle F-27135 Verneuil sur Avre **FRANCE** Tel +33 2 3222 3000 Fax +33 2 3260 1479

info@transvideo.eu

www.transvideo.eu

transvideo **Quick Start Guide** Starlite // ARRI Several patents pending

www.transvideo.eu

▶ Warning & Caution

This product must be used in a correctly grounded electrical environment; ground defects can create severe problems to the equipment, the picture quality and even cause danger for the user.

Copyright law and international treaties protect this product, its design and its software. One or several international patents apply to the StarliteHD. Unauthorized reproduction or distribution of this product or its design or its software or any portion of them, may result in severe civil and criminal penalties, and will be prosecuted to the maximum

Transvideo uses a specific cable for the StarliteHD. User must be extremely careful with the wiring of custom cables. Using custom or 3rd party cables may damage the product, and void your warranty.

Warranty is void as the product is opened. The unit contains electrostatic sensitive devices, which can be damaged or destroyed if you touch them. High voltage is present in the product and there is some risk of electric shock if opened by a non-accredited technician. Standard ESD procedures must be strictly followed during disassembly/re-assembly of the unit.

The user and/or technician assumes full responsibility or any risk of property damage, bodily injury, or even death arising out of the use or disassembly or repair of this equipment. In no event shall Transvideo S.A. or its local representatives be liable to a user, technician or third party for any injury, loss of any income or any damage of any kind resulting from the use of or work

▶ Home View - Smart Corners Starlite */> **Displays Smart Corners Smart Corners Smart Corners** User assigned tools User assigned tools Menu / Smart Corners Menu / Smart Corners **ARRI Mode** Rec - Play & Snap buttons Visible only when ARRI 1:1 Zoom zone (pixel to pixel) Camera detected Tap to zoom in or zoom out Slide to move the zoomed picture






System Menu



▶ Tools menu

Starlite */>


144TD0004 - Rev 01-0203 May 2017



▶ Smart Corners Menu

Starlite */D

To assign a tool to a smart corner: select a tool, then choose the corner to which you want to assign it.



▶ Adjust Menu

Starlite */D



Slide to adjust Luminosity, Brightness or Contrast then validate by pushing

▶ Virtual Horizon

Starlite */D



From the main menu, select Tools icon. then activate Virtual Horizon. When the horizontal bar is displayed on the top of the monitor screen, tap on CAL button.

This will calibrate the digital bubble. The green bubble indicates that your monitor is on level.

10

Metadata

Starlite */D

11

► Histogram / Waveform / Vectorscope

Starlite */D



Displays available metadata embedded in the SDI signal.

Metadata is camera dependent.



Displays available measurment tools. Histogram & Waveform can be pinned on the picture by simply touching their representation on this screen.

12

Tap the waveform to change size.



Waveform can be displayed either fullscreen or overlaying the live image.

Peaking Starlite */D



Peaking is applied to the image area located between the two vertical bars.

16

▶ Recording / Playing



* All supported standards.

▶ Record / Playback / Converting

File Gallery Select for playback Home view

Navigation Slide on thumbnails to navigate

Convert output format


h.264 to mp4 (default) Press the "Convert" icon then select the video in the

Starlite */>

Starlite */D

* Please note that previously converted files with the same name will be overwritten.

▶ Recording / Playing



Starlite 4/D

17


Starlite 1/2

Starlite */D

Auto REC

15

Starlite */D



Delete the latest record

From the main menu, select Tools then activate Auto REC

If you need the quick menu, also activate AutoREC Control

Play, Go, Delete icons should appear after the camera stops recording

Auto REC control is only available for build 112 and later. Play the latest record You can see the build version on the monitor startup screen.

18

▶ Mechanics & connectors



Transvideo mounting system with 1/4-20 thread To attach the monitor to 3D Swing Arm - To mount a Battery Adapter

▶ Technical specifications

Video input	1 x 3G / HD / SDI
Video output	1 x 3G / HD / SDI
Supported Standards	3G: 1080 / 50p, 60p HD: 1080 / 50i, 60i 1080 / 24p, 25p, 30p 1080 / 24psf, 25psf 720 / 25p, 30p, 50p, 60p SDI: 525 / 60i 625 / 50i
Display type & size	AMOLED - 5 inches
Pixels	Picture zone 1280 x 720
Contrast ratio	3400:1
Viewing angle	+80° H & V

Starlite */D

Color temperature	D56
AvengerLeveler™	yes
Power 6 to 30V DC	Lemo EGG.0B.305 CLL 1 Gnd 2 +V DC 3 Reseved 4 Can L 5 Can H
Power Cons.	6W
SD card slot	yes
Dimensions (w x h x d)	144 x 68 x 27 mm 5,66 x 2,67 x 1,06 inches
Weight	< 200g / 0.5 lbs

Starlite */>

20

▶ ARRI camera connectors Pin-Outs



ALEXA Mini EXT Lemo 1B 307 1 Can1 H 2 Can1 L 3 Can2 H 4 Can2 L 5 VBat (1A max) 6 Gnd 7 R/S

Note: All pin-outs for camera interfaces appear as seen by the user.

Configuration

Brightness max 380 Nits

You can change your StarliteHD configuration which gives ability to:

- Convert the output format from h.264 to mp4 (default) or mkv files.
- Adjust the compression level and to choose intra mode for coding.
- Choose a default file name for your clips.
- And More.

User presets options are available via our website. The generated settings are installed onto the SD card.

For more information, visit http://www.transvideo.eu/support-StarliteHD

2.2

▶ How to Update

Starlite */D

2.1

23

Place the SD card into your computer. Visit: http://www.transvideo.eu/starlitehd-upd Download and uncompress the latest software release (the downloaded file is zip format) using your archive utility application. Open the uncompressed folder then copy the file maj.tar.gz and paste it at the root of the SD card. *Do not rename the update file on the SD card*

Insert the SD card into the monitor. Turn the monitor ON, then push down the menu button.

Select the Settings icon then select Update. Validate your choice and wait...

During the update, you can read the following information on the screen. - Full system update: may require more than 30 minutes.

Applicative update in progress.

Do not disconnect your monitor from the power supply. We recommend the StarliteHD is connected to Mains Power for Updates

After a successful update, the monitor displays "Your monitor is up to date".

If an error occurs, a report is generated. You can read our online version at http://www.transvideo.eu/support-StarliteHD

▶ Accessories / Cables



Mini 3D Swing Arm for ARRI™ Includes a special 3/8"-16 male thread on the base. P/N 918TS0261



Battery Back





Battery Back For Canon BP 900 series 7.2V LI-ION. P/N 918TS0273

D-Tape/Lemo5 power cable P/N 906TS0187

P/N 906TS0188

Starlite */D Viewfinder Adapter



3x aspherical magnifier Converts the StarliteHD to a viewfinder P/N 918TS0266



Protects the screen from direct sun. P/N 918TS0265



Lemo6/Lemo5 cable P/N 906TS0189